

New Firmware Release Notes

Release date: 11. 1. 2016
Previous version(s): Firmware 4.7, ASD Client 10.3
New version(s): Firmware 4.8, ASD Client 10.4
Devices: MP91, MP100, MP155, MP165, MP200, MP300, MP360, MP600, AL80GE

Changelog:

Firmware 4.8	<ul style="list-style-type: none">- fixed: blocking of HTTP or SNMP server by supervise line overloading by broadcasting operation- fixed: communication error with modem by repeating a command for modem- fixed: incorrect ACM turn off from manual mode- added: support for channel 20 MHz according to standard ETSI
ASD 10.4	<ul style="list-style-type: none">- fixed: doubled shortcut CTRL+L in the window Power TX- fixed: backup error of VLAN and QoS setting by the routing MP155/100 series- fixed: not retuning of a local station by using of scroll bar (set TX / set RX)- added: support for channel 20 MHz according to standard ETSI