

## Firmware Release Notes

Release date: 14.8.2015  
Previous version(s): Firmware 4.6, ASD 10.2  
**New version(s): Firmware 4.7, ASD 10.3**  
Devices: MP100, MP300, MP360, MP400, AL80GE

### Changelog:

Firmware 4.7	<ul style="list-style-type: none"><li>- added: support for frequency band 18 GHz (AL18F MP300/400)</li><li>- added: range of RX filter and modem fw version to Summary</li><li>- fixed: incorrect modem initialization after link expiration when turned off</li></ul>
ASD 10.3	<ul style="list-style-type: none"><li>- added: range of RX filter and modem fw version to Summary</li><li>- added: support for frequency band 18 GHz (AL18F MP300/400)</li><li>- changed: conditions for NMS line routing in QoS Properties</li><li>- changed: small language changes in messages in QoS Properties</li><li>- fixed: incorrect layout of Line 2 column in Ethernet Properties for MP300</li></ul>